# Files and Rasps.





Bastard.


#### NOTICE.

For Castings, Wrought Iron, Brass, Composition Metals and like material,
order Bastard Cut.



Mill Saw Bastard


For Steel and Part Finish to Iron Work, order Second Cut.



Second Cut.

For Finishing to a Good Surface, order Smooth Cut.

For an Extra Finish, order Dead Smooth.





Wood Rasp



Smooth.

It is always to consumers' advantage to order special cuts for special work.

See Additional Illustrations on Pages 537, 538, 539 and 540.

SEE PRICE LIST ON PAGE 541.



Horss Rasp.

### KEARNEY & FOOT Co.

Should a File be Defective, by taking it to the Parties from whom Purchased, a Perfect one will be Given in Exchange, Free of Charge.

Hand Dead Smooth Gin. 304 Halfrannd Bastard 6 in. 196 Round Bustard 6112. 1195 Flut and Cut Gin. 102 Flat Bastand Gin. Not Hand Smooth Gir. N'3 (K&F) KÆE KAF KXF

Equaling Bastard 6 in. Nº 13

(K&F)

Pillar Bastard 6in. Nº 14

(K&F)

Square Bastard 6in. Nº 15


Crossing Bastard 6in. Nº 16

Cabinet File bin. Nº 17

(K&F)

Halfround Wood Pasp 6 in. Nº 18

Cabinet Rasp 6in. Nº 19



# Kearney & Foot Co.,

# Files and Rasps.

For Illustrations, see Pages 536 to 540.

BASTARD.	4 In.	5	6	7	8	9	10	11	12	13	14	15	16	18	20
Mill Saw, and Round	\$1 80	2 00	2 25	<sup>2</sup> 55	2 90	3 30	3 80	4 50	5 40	6 50	7 80	9 30	11 00	15 10	20 40
Mill Saw, One Round Edge	194	2 15	2 42	2 74	3 12	3 55	4 09	4 84	5 81	6 99	8 39	10 00	11 83	16 23	21 93
Flat and Square	2 00	2 20	2 50	2 90	3 40	4 00	4 70	5 60	6 70	8 00	9 50	11 20	13 10	17 65	23 20
Hand	2 25	2 50	2 80	3 20	3.70	4 35	5 20	6 30	7 50	8 90	10 50	12 30	14 30	19 20	25 30
Half Round	2 50	2 80	3 20	3 70	4 30	5 00	5 80	6 70	7 80	9 10	10 60	12 40	14 50	19 60	26 00
SECOND CUT.															
Mill Saw, and Round	2 15	2 40	2 65	3 00	3 40	3 85	4 40	5 20	6 20	7 45	8 90	10 60	12 50	16 90	22 85
Flat and Square	2 40	2 60	2 95	3 40	4 00	4 70	5 45	6 50	7 70	9 15	10 90	12 75	14 85	19 75	26 00
Hand	2 70	3 00	3 30	3 75	4 35	5 10	6 00	7 30	8 6o	10 20	12 00	14 00	16 20	21 50	28 35
Half Round	3 00	3 35	3 80	4 35	5 00	5 85	6 75	7 75	9 00	10 40	12 10	14 15	16 50	22 00	29 10
SMOOTH.											-		_		
Rouud	2 40	2 65	2 95	3 30	3 70	4 20	4 80	5 65	6 75	8 05	9 65	11 45	13 40	18 10	24 50
Flat aud Square	2 65	2 90	3 25	3 75	4 35	5 10	5 90	7 05	8 40	10 00	11 80	13 75	16 00	21 20	27 85
Haud	3 00	3 30	3 65	4 15	4 75	5 55	6 55	7 95	9 40	11 00	13 00	15 10	17 50	23 00	30 35
Half Round	3 30	3 70	4 15	4 80	5 50	6 40	7 30	8 45	9 75	11 25	13 10	15 25	17 70	23 50	31 20
								=		-		<u> </u>			
RASPS.															
Cabinet Files			4 20	5 00	6 10	7 30	8 75	10 40	12 30	14 50	16 90	19 60	22 50		(
Cabinet Rasps			6 00	7 00	8 20	9 60	11 20	13 00	15 00	17 20	19 60	22 20	25 00		
Flat & Half Round Wood Rasps			4 20	5 00	6 10	7 30	8 75	10 40	12 30	14 50	16 90	19 60	22 50		
Farriers' or Horse				<b>.</b>			6 50	7 50	8			15 00		23 70	
Tauged Horse				<b>.</b>			9 00	10 25	12 00	14 00	16 50	19 50	23 00		
Shoemakers' Rasps, Flat			4 60	5 30	6 10	7 00	8 00	9 10	10 30	11 60	13 00				
SAW FILES.	3 In.	3)2	4	412	5	5 /2	6	7	š	9	10	11	12	13	1:1
Tapers Slim Single Cut	\$1 20	I 20	1 30	I 45	1 70	1 90	2 10	2 50	3 00	3 70	4 50	5 50	6 80	8 30	10 00
Tapers Regular Single Cut	1 10	1 10	1 20	1 40	1 70	2 00	2 40	3 00	3 80	4 60	5 70	7 20	9 00	11 00	13 20
Tapers Double Cut to Point	1 60	1 60	I 75	2 00	2 40	2 75	3 25	4 00	4 95	5 90	7 10	8 80	10 80	12 90	15 20
Pit Saw Single Cut	2 10	2 10	2 20	2 30	2 50	2 80	3 20	3 70	4 30	5 00	5 80	6 70	7 70		